



Planning

- Ensure you have all materials
- 6" flex and collar
- 8" flex and collar
- Cutting tools
- Drill
- Pliers
- Steel Tape
- Plan placement of 8" intake collar
- Plan placement of 6" outflow collar


(try to put at least 8' between the two when possible)








Cutters can now use the hole to begin cutting out the 6" outflow into the cold air return of the furnace




Cut along the traced marker line





A 6" hole should now be cut into the cold air return right before it enters the furnace



Repeat the previous 4 steps to cut out the 8" intake hole






Constructing Bypass Flex

Place 6" flex to the 6" collar



- Fit flex around collar
- Compress several inches of flex around the collar for a sure fit



Secure flex to the duct with self tapping metal screws



3 screws evenly spaced will secure the flex to the collar





Use steel tape to seal the flex to the collar airtight.



Connecting Bypass Flex

Connect the 6" outflow collar to the cold air return using self tapping metal screws




4 screws are needed to completely secure the collar to the return



Steel tape around the 6" collar to make the connection to the cold air return airtight






Repeat 'Constructing Bypass Flex' and 'Connecting Bypass Flex' steps with the 8" intake flex and collar



NOTE: The 8" intake collar will need more steel tape as it is larger





Plan placement of HEPA System

(ensure that the unit can be accessed for filter changes)



Cutting the Connections

- Drill 2 holes close together
- With pliers, ream the 2 holes together to make a bigger hole

